

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Biloxi Decon Area (Yates Construction)	Facility Location ID:	BD01
Assessment Date :	8/30/2010	Incident Name :	BP Spill
Physical Location :	215 Michael Industrial Blvd		
City, State :	Biloxi , MS	County :	Harrison

ASSESSMENT INFORMATION

General Site Information and Observations			
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
4. If yes, was it adequately addressed?			
5. How many samples were collected?			
Additional Comments : No oily boom has been processed at this facility. 11 roll-offs on non-contaminated algae boom were staged for processing along with a large amount of loose boom which was being unloaded from a barge. 2 roll-offs containing damaged non-contaminated boom were noted. ERM representative, Mr. Leon, said that the damaged boom which cannot be cleaned and reused, will be disposed of, not recycled. Currently, all liquid and solid wastes from decon operations are being manifested as non-contaminated.			